

 **Report**
An Unsafe Product **Business**
Register & Respond **Search**
Recalls & Reports[About](#)[Questions](#)

Due to the extraordinary circumstances surrounding COVID-19, some of the remedies identified in recall press releases may not be available at this time. Consumers should check with recalling firms for further details.

It is important to remember that CPSC and recalling firms urge consumers not to use recalled products.

Search

Narrow Your Results By:

[Clear Filter](#)

Type

- ☒ All Types
- ☐ Recalls/Repairs

Date

- ☒ All Dates

to

Product

[All Products](#)

» [Recall Product Category](#)

» [Recall Product SubCategory](#)
Furnaces

Company

Brand

Model

Injury Information

Location

Victim's Age

[Advanced Search](#)

[Settings](#)

Showing 1 – 6 of 6 results.

Show: Fewer Details | [More Details](#)

Sort by: Date | [Relevance](#) [Print](#) [Share](#) [Export](#)

RECALL | 1/18/2001

[CPSC Recommends Carbon Monoxide Alarm for Every Home](#)

CPSC Recommends Carbon Monoxide Alarm for Every Home After a recent rash of carbon monoxide poisonings – including incidents in Maryland, Pennsylvania and New Jersey the U.S. Consumer Product Safety Commission (CPSC) is repeating its recommendation that every ...

RECALL | 11/1/1993

[York Offering To Replace All Heatpipe Furnaces](#)

November 1, 1993 Release # 94-004a PRODUCT: Approximately 4,000 Borg-Warner, Luxaire, Fraser-Johnson, and Moncrief "Heatpipe" furnaces manufactured and sold by York International Corporation between 1984 and 1988. PROBLEM: Parts of the furnace and vent ...

RECALL | 11/1/1989

[Coleman Urges Inspection Of Pre-1971 Solar Pak Furnaces To Reduce Potential For Carbon Monoxide Poisoning](#)

November, 1989 Release # 90-008 WASHINGTON D.C.-
-An inspection and discount replacement program announced last year for Model 8600 Solar Pak mobile home furnaces is being continued by the Coleman Company Manufactured Housing Products Division of Wichita, ...

RECALL | 10/26/1988

[Coleman 8600 Solar Pak Mobile Home Furnaces Replacement](#)

Coleman 8600 Solar Pak Mobile Home Furnaces Replacement NEWS from CPSC U.S. Consumer Product Safety Commission Office of Information and Public Affairs Washington, DC 20207 FOR IMMEDIATE RELEASE October 26, 1988 Release # 88-88 CPSC Warns Of Potential For ...

RECALL | 2/3/1987

[Home or Miller Gas-Fired Furnaces for Mobile Home Replacement](#)

Home or Miller Gas-Fired Furnaces for Mobile Home Replacement Roof vent caps on certain HOME or MILLER brand gas-fired furnaces installed in mobile homes are being replaced free of charge by Lear Siegler, Inc., as a precaution against accidental carbon ...

RECALL | 6/9/1981

[Mobile Home Furnaces Repaired by HOME](#)

Mobile Home Furnaces Repaired by HOME NEWS from CPSC U.S. Consumer Product Safety Commission Office of Information and Public Affairs Washington, DC 20207 FOR IMMEDIATE RELEASE June 9, 1981 Release # 81-017 Carbon Monoxide Gas Hazard Prompts Repair Program ...

⏪ ⏩ [1] ⏪ ⏩

CPSC does not guarantee the accuracy, completeness, or adequacy of the contents of the Publicly Available Consumer Product Safety Information Database on SaferProducts.gov, particularly with respect to information submitted by people outside of CPSC.